

**MEMORANDUM FOR THE RECORD**

**SUBJECT: 24TDA07 MFR Fish unit 1 Temporarily Out of Service**

On 20 May @ 0548 Fish Unit 1 tripped out of service during a routine bus swap from lines 1&2. A proportion valve in the governor oil system was found to be stuck in place causing the unit to alarm and shutdown. The AWS backup system was activated to provide supplemental flow for fish attraction in the East fish ladder from 0838 -1056 while the valve was repaired. At 1100 fish unit 1 returned to service and the AWS backup system shut off.

- A. Species – NA
- B. Origin – NA
- C. Length – NA
- D. Marks and tags – NA
- E. Marks and Injuries found on carcass –NA
- F. Cause and Time of Death – NA
- G. Future and Preventative Measures

Sincerely,

Project Fisheries