**CENWP-ODO** Date: 2022-06-07

## MEMORANDUM FOR THE RECORD 22 LMN 08 Spillway Gate 5 Coupler

**SUBJECT:** Spillway gate 5 FOOS for motor coupler repair

**Narrative:** On the afternoon of June 7, 2022, Lower Monumental Dam spillway gate 5 would not operate and was declared forced out of service at 12:12. Repairs began immediately to repair the coupler and were able to return the spillway gate to service at on June 8, 2022 at 0830. Apparently, the failure of the coupler for spillway gate 5 are like those noted in 22 LMN 04 Spillway gate 4, 5 & 6 couplers, however, a different type of lock tight was needed to repair the gate for a more permanent fix.

## **Timeline – Duration:**

- A. Species NA
- B. Origin NA
- C. Length NA
- D. Marks and tags NA
- E. Marks and Injuries found on carcass NA
- F. Future and Preventative Measures Continue preventative and annual maintenance.
- G. Photos: None.

Denise Griffith
Supervisory Fish Biologist
Lower Monumental Dam
(509) 282-7211
Denise.S.Griffith@usace.army.mil