Sent: Friday, June 28, 2019 2:12 PM

Subject: Official TMT Coordination: Lower Monumental Dam Spill Pattern

TMT Members and Alternates,

At Lower Monumental Dam (LMN), since the start of summer spill operations (June 21 at 0001 hours) until today (June 28 at 1200 hours) the Corps was not spilling in accordance with the correct spill pattern due to human error. During this period the Corps was spilling in accordance with spill pattern, "Table LMN-8. Uniform Spill Patterns with RSW," when the Corps should have been spilling in accordance with, "Table LMN-7. Bulk Spill Pattern with RSW." The Corps discovered this error today and at 1200 hours LMN began spilling in accordance with "Table LMN-7. Bulk Spill Pattern with RSW." The Corps will continue operating LMN spill patterns as described in 2019 Fish Passage Plan (2019 FPP) through the end of summer spill operations on August 31, at 2359 hours. Additional information regarding LMN spill pattern operations may be found in the 2019 FPP on the following website on pages LMN 14-16 and LMN 30-35.

http://pweb.crohms.org/tmt/documents/fpp/2019/final/FPP19 07 LMN.pdf

LMN spillbay data may be found on the following website.

http://pweb.crohms.org/tmt/documents/ops/spillbay/

As described in the 2019 Fish Operations Plan, LMN has been spilling 17 kcfs 24 hours/day since the start of summer spill on June 21. The Corps will provide the TMT with an update on this operation at our next TMT meeting on July 10.

1