

MEMORANDUM FOR THE RECORD: 19 LWG 03 Emergency Debris Spill

SUBJECT: Lower Granite emergency debris spill.

April 12 at about 0600 hours a large mat of debris was reported in the Lower Granite spillway section of the forebay. There was no debris in the spillway section of the forebay area observed during the fish ladder inspection at 1110 hours April 11. The mat was estimated to be about 5.22 acres. An emergency debris spill occurred between 0757-0925 hours April 12. A photo of the debris taken at about 0630 April 12 shows the forebay looking north and standing between the RSW and spillbay 2. The navigation lock guide wall in the upper left is 550 feet long. The clear area in the lower right is due to RSW operation. Photo does not capture the debris accumulation in front of the RSW or along the shear boom.

- A. Species – N/A
- B. Origin – N/A
- C. Length – N/A
- D. Marks and tags – N/A
- E. Marks and Injuries found on carcass – N/A
- F. Cause and Time of Death – N/A
- G. Future and Preventative Measures – N/A

Sincerely,
Elizabeth Holdren
Supervisory Fisheries Biologist
Lower Granite Project
Ph. (509) 843-2263

