

**MEMORANDUM FOR THE RECORD****SUBJECT: 20BON55 Adult Fish Facility Chinook Mortality.**

On Tuesday, July 21<sup>st</sup>, CRITFC biologists notified Project Biologists of two Chinook mortalities found on the valve 15 trash rack of the AFF. The fish were scanned for PIT tags, inspected for any abnormal injuries, and returned to the river. Fish #1 had two holes in one side; one hole behind the gill plate and one in the side of the mouth. Fish #2's picture turned out blurry but was included for size comparison.

#1

- A. Species – Chinook Salmon (*Oncorhynchus tshawytscha*)
- B. Origin – Unknown.
- C. Length – Approximately 34 cm.
- D. Marks and tags – None.
- E. Marks and Injuries found on carcass – Holes in the side behind the gill plate and on the mouth
- F. Cause and Time of Death – Unknown
- G. Future and Preventative Measures – None.



#2

H. Species – Chinook Salmon (*Oncorhynchus tshawytscha*)

I. Origin – Unknown.

J. Length – Approximately 26 cm.

K. Marks and tags – None.

L. Marks and Injuries found on carcass – None

M. Cause and Time of Death – Unknown

N. Future and Preventative Measures – None.



Sincerely,  
Project Fisheries