

MEMORANDUM FOR THE RECORD**SUBJECT: 21 JDA 11 Broken Avian Lines**

At approximately 1500 on Thursday October 7th contractors, working on the line outages, lost control of a transmission line (while attaching to the line-4 tower). This line fell, contacted the powerhouse roof, and broke six (6) avian lines. These lines were attached to the powerhouse between monoliths 12 & 13. The contractor retrieved the lines and replacement of the lines by the contractor will be coordinated with project personnel. Fortunately, no one was injured.



Figure 1. General location of broken avian lines.

- A. Species – N/A
- B. Origin – N/A
- C. Length – N/A
- D. Marks and tags – N/A
- E. Marks and Injuries found on carcass – N/A
- F. Cause and Time of Death – N/A
- G. Future and Preventative Measures – N/A

Sincerely,
JD Project Fisheries