

MEMORANDUM FOR THE RECORD

SUBJECT: *24JDA13 Spillway Crane OOS and Unable to Close TSW-18*

On 29 August 2024 at approximately 1400, the JDA spillway crane went out of service due to a transformer failure. Unfortunately, there isn't a replacement part onsite, and due to the specifics of the part, it may be difficult to replace. Crews were able to close the TSW in spillbay-19 but were unable to close the TSW in spillbay-18. There is no other way to close the TSW, as using a mobile crane would be unsafe.

In order to maintain the FPP spill requirement of 20-KCFS, spillways 2, 3, 4, and TSW-18 was open until 1 September 2024. Starting 1 September 2024 only spillway 2 will be open with the TSW, and total spill will be approximately 10-12 KCFS. Operations will continue to utilize the TWS open unit priority table until the TSW can be removed and the spillway gate is closed.

- A. Species – NA
- B. Origin – NA
- C. Length – NA
- D. Marks and tags – NA
- E. Marks and Injuries found on carcass – NA
- F. Cause and Time of Death – NA
- G. Future and Preventative Measures- NA

Sincerely,

Project Fisheries