

MEMORANDUM FOR THE RECORD: 21 LWG 07

SUBJECT: RSW Log Removal

Removal of an entangled log in the RSW debris boom was necessary to maintain safe fish passage and prevent damage to the forebay boom (see photo). Initial efforts to clear the log failed and it was determined that the RSW would need to be closed for removal. April 28 LWG operator began closing the RSW at 0658 hours and returned the RSW to service at 0720 hours. Successful removal of the log took less that 10 minutes.

- A. Species – NA
- B. Origin – NA
- C. Length – N/A
- D. Marks and tags – NA
- E. Marks and Injuries found on carcass – NA
- F. Cause and Time of Death – NA
- G. Future and Preventative Measures – Continue to complete regular inspections of spillway gates and flow conditions.

Sincerely,
Elizabeth Holdren
Lead Supervisory Fisheries Biologist
Walla Walla District
Lower Granite Project
Ph. (509) 843-2263



Photo 1. Forebay south side of RSW.